HISTORIC AMERICAN LANDSCAPES SURVEY

INDEX TO PHOTOGRAPHS

OLOMPALI STATE HISTORIC PARK, NATURAL LANDSCAPE & BURDELL GARDEN & GROUNDS Olompali State Historic Park U.S. Highway 101 Novato vicinity Marin County California

HALS CA-4

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Brian Grogan, Photography + Preservation Associates, July 2007

- CA-4-1 ENTRANCE ROAD LINED BY OAK TREES AND POMEGRANATE HEDGE ON RIGHT. LOOKING SE.

 CA-4-2 ALTERNATE VIEW OF POMEGRANATE HEDGE AND OAKS TREES. LOOKING EAST.

 CA-4-3 LAWN AREA ADJACENT TO ENTRANCE ROAD. HOUSE IS AT RIGHT REAR, OBSCURED BY LARGE OAK TREE. LOOKING WNW.

 CA-4-4 POND BASIN NEAR ENTRANCE ROAD WHICH IS BEYOND TREES AT DIGHT. LOOKING SOLUTION.
- TREES AT RIGHT. LOOKING SOUTH.
- CA-4-5 ROCKERY AT SOUTH END OF GARDEN. ENTRANCE ROAD SEEN THROUGH TREES AT RIGHT REAR. LOOKING SE.
- CA-4-6 LONG VIEW OF GARDEN AREA SEEN FROM NEAR ROCKERY.
 NOTE STAIRS AT LEFT AND FOUNTAIN AT CENTER REAR.
 LOOKING NORTH.
- CA-4-7 MAIN HOUSE AND ENTRANCE STAIRS SEEN FROM TOP OF STONE STAIRS TO GARDEN AREA. LOOKING WEST.
- CA-4-8 VIEW OF ENTRANCE ROAD FROM FRONT OF HOUSE. NOTE STAIRS TO GARDEN ON LEFT, ROAD TO RIGHT, AND POMEGRANATE HEDGE AT RIGHT REAR. LOOKING SE.

OLOMPALI STATE HISTORIC PARK, NATURAL LANDSCAPE & BURDELL GARDEN & GROUNDS HALS No. CA-4 INDEX TO PHOTOGRAPHS (Page 2)

CA-4-9	CENTER GARDEN AREA WITH STAIRS AT LEFT, PATH RIGHT CENTER, AND FOUNTAIN AT RIGHT REAR. LOOKING NNW.
CA-4-10	DETAIL VIEW OF GARDEN STAIRCASE WITH FOUNTAIN AT CENTER REAR. SAME CAMERA POSITION AS PHOTOGRAPH NO. CA-4-7. LOOKING NE.
CA-4-11	GARDEN STAIRCASE WITH HOUSE AT REAR. LOOKING NW.
CA-4-12	GARDEN STAIRCASE WITH HOUSE AT RIGHT REAR. LOOKING WEST.
CA-4-13	GARDEN VIEW FROM FRONT OF HOUSE. NOTE FOUNTAIN AT CENTER IN TREES. LOOKING NE.
CA-4-14	FOUNTAIN. LOOKING NE.
CA-4-15	FOUNTAIN ALTERNATE VIEW. LOOKING NNW.
CA-4-16	FOUNTAIN AND GARDEN LANDSCAPING. NOTE TERRACING. LOOKING NW.
CA-4-17	VIEW ALONG GARDEN PATH. NOTE TERRACED LANDSCAPE. ROAD AT LEFT. LOOKING NW.
CA-4-18	STONE LINED CHANNEL AT NORTH END OF GARDEN. LOOKING WSW.
CA-4-19	STONE CULVER UNDER ROAD. LOOKING WSW.
CA-4-20	AMERICAN CHESTNUT TREE AT REAR OF HOUSE. LOOKING WEST.